



### Construction:

manufactured in high quality synthetic rubber, the wall thickness of approx. 3 mm enables hard stress

### Characteristics:

- extends beyond the coupling tail reducing impact damages when the hose is dropped or dragged
- fits tightly behind the coupling collar preventing ingress and build up to mud between the coupling and hose
- 3 mm wall thickness provides resistance to impact damages
- prevents potential hand injuries during coupling connection
- can easily be fitted to existing hose assemblies

## HOSE CUFF

impact and abrasion protection for hose assemblies

